Oil Field Environmental Incident Summary

Responsible Party: DENBURY ONSHORE, LLC **Well Operator:** DENBURY ONSHORE, LLC

Well Name: FOSSUM 14 1

Field Name: INDIAN HILL Well File #: 10855

Date Incident:5/7/2014Time Incident:10:03Facility ID Number:County:MCKENZIETwp: 153Rng: 101Sec: 35Qtr:

Location Description:

Submitted By: Mark VanGrinsven Received By:

Contact Person: Mark VanGrinsven

5320 LEGACY DR

PLANO, TX 75024-3127

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:2 MileDistance Nearest Water Well:2 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

116 Barrels 75 Barrels 116 barrels

Brine Other

Oil

Description of Other Released Contaminant:

Inspected: Written Report Received: 2/17/2016 Clean Up Concluded: 5/4/2015

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

A vac truck was dispatched and recovered 75 barrels. The affected area will be washed with hot water and the water recovered. The remaining oil/contaminated soils will be removed. This and similar valves are in the process of being re-fitted with spring loaded slam valves to prevent any similar reoccurences.

Wastes Disposal Location: Fluids will be returned to the oil tank and soils will be disposed by contractor at an approved landfill.

Agencies Involved:

Updates

Date: 5/7/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from an on-location valve/piping leak remained on location within the diking, according to the report. NDIC retains oversight.